

Lisle Community Unit School District 202

Vision 202


Chapter Two: Facility Master Planning



Schiesher Elementary School

Building Tour

Saturday, February 27, 2016



Observations

.....


Exterior

District staff and/or Vision 202 participants identified the following positive **exterior** features of Schiesher Elementary School:

- Updated Playground
- New Sign
- Close to Downtown, JH, HS

The following challenges were also noted for the Schiesher **exterior** and/or site grounds:

- 1 Main entrance is in the rear of the building and not easily accessible for visitors, emergency responders, garbage service, or deliveries
- 2 Parking lots are in need of resurfacing and more parking capacity is needed
- 3 Single lane access/blind spot to back parking lot is a safety concern
- 4 Buses are unable to fit around the circle drive. The tight turn is difficult for buses to negotiate
- 5 Limited parking for visitors, meetings and/or events. Visitor parking located across Kingston Ave. and is limited following snow falls
- 6 Drop-off/pick-up location is located in the visitor parking lot across Kingston. Students must cross the street with the assistance of a crossing guard
- 7 Basketball court location is near Kingston Ave. & doubles as bus parking for Kindergarten bus pick up restricting the use of the paved area
- 8 Playground is located next to the driveway with no physical barrier
- 9 Sight lines are limited due to the different levels of the play fields and playgrounds
- 10 No outdoor storage for recess equipment. Storage shed used to house outdoor maintenance equipment is located in the staff parking lot



Interior

We are proud of the environment we've created for our students here at Schiesher. While there are challenges, we strive to adapt the spaces to maximize the impact on student learning.

District staff and/or Vision 202 participants identified the following positive **interior** features of Schiesher Elementary School:

- Large Gym with a stage
- Access to technology
- Wide hallways

Observations

.....

Interior

The following challenges were also noted for the Schiesher building **interior**:

- 1 Main Entrance is located in the back of the building and lacks a secure entry point
- 2 The "flow" or layout of the building, the hallways do not direct visitors back to the main office for exit, congestion at "T" points in the hallways
- 3 Appropriate size of Kindergarten classrooms and the lack of appropriately sized washroom facilities
- 4 Classrooms in general are undersized and lack sufficient electrical outlets
- 5 Location of and access to services in upper level area
- 6 Access to materials in LRC and effective use of space due to sunken middle area
- 7 Special Services space for additional academic support & instruction
- 8 When the lift is broken, the only access is via outside ramps to the upper hallway
- 9 Band room is limited in space and only accommodates small groups. Instrument storage is in the main hallway
- 10 Nurses office is limited in size and private facilities. Office only accommodates a small number of students
- 11 The noise level in the LRC is often high due to the adjacency to the Gym
- 12 Lack of large group collaboration/project space
- 13 Appropriate storage space for Music & Art classrooms

Lisle Community Unit School District 202

Vision 202

Chapter Two: Facility Master Planning



Community Engagement Session #3

Review & Evaluate Facility Options

Wednesday, March 23, 2016

7-9pm · Lisle Jr. High School

RSVP appreciated, but not required at:

bit.ly/vision202rsvp or scan 

Session #4

Financial Implications of Facility Options

Tuesday, April 19, 2016

Lisle Jr. High School

7-9pm

Session #5

Key Findings & Facility Options Recommendations

Thursday, May 19, 2016

Lisle Jr. High School

7-9pm

Stay Connected with Vision 202!



www.vision202.org



Like us at
Lisle Vision 202



@Vision_202

